\$500.018041

Col Col

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

DEVICE

U.S. Patent No.: 7,265,377 B2

Issued: September 4, 2007

January 28, 2008

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450 Certificate

JAN 3 I 2008

Of Correction

REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

01/36/2608 JADDO1 66886

66536683 7565377

01 FC:1811

100.00 OP

Patentees' undersigned attorney may be reached in our Costa Mesa,
California office by telephone at (714) 540-8700. All correspondence should continue to
be directed to our address given below.

Respectfully submitted,

Damond Validais
Attorney for Patentees
Registration No.: 52,310

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 Facsimile: (212) 218-2200

FCHS_WS 1936455v1

CERTIFICATE OF CORRECTION

PATENT NO. : 7,265,377 B2

DATED: September 4, 2007

INVENTOR(S): Kubota, et al.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 4:

Line 33, "semiconductor;" should read -- semiconductor, --.

COLUMN 6:

Line 7, "electrode;" should read -- electrode, --.

COLUMN 12:

Line 6, "cosideration" should read -- consideration --.

COLUMN 14:

Line 67, "an deposition" should read -- a deposition --.

COLUMN 17:

Line 60, "line (b)" should read -- line (b). --.

COLUMN 18:

Line 17, "form" should read -- from --; and Line 41, "The" should begin a new paragraph.

COLUMN 20:

Line 53, "an deposition" should read -- a deposition --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. <u>7,265,377 B2</u>

No. of add'l. copies @ 30¢ per page



CERTIFICATE OF CORRECTION

PATENT NO.

: 7,265,377 B2

DATED

: September 4, 2007

INVENTOR(S) : Kubota, et al.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 21:

Line 25, "insulator;" should read -- insulator, --.

COLUMN 22:

Line 53, "electrode;" should read -- electrode, --.

FCHS_WS 1936445v1

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

PATENT NO. 7,265,377 B2

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82) 1936445v1(Form#30)

CERTIFICATE OF CORRECTION

PATENT NO.

: 7,265,377 B2

DATED

ويكس

: September 4, 2007

INVENTOR(S) : Kubota, et al.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 4:

Line 33, "semiconductor;" should read -- semiconductor, --.

COLUMN 6:

Line 7, "electrode;" should read -- electrode, --.

COLUMN 12:

Line 6, "cosideration" should read -- consideration --.

COLUMN 14:

Line 67, "an deposition" should read -- a deposition --.

COLUMN 17:

Line 60, "line (b)" should read -- line (b). --.

COLUMN 18:

Line 17, "form" should read -- from --; and

Line 41, "The" should begin a new paragraph.

COLUMN 20:

Line 53, "an deposition" should read -- a deposition --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) 1936445v1(Form#30)

PATENT NO. <u>7,265,377 B2</u>

No. of add'l. copies @ 30¢ per page



CERTIFICATE OF CORRECTION

PATENT NO.

: 7,265,377 B2

DATED

: September 4, 2007

INVENTOR(S) : Kubota, et al.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 21:

Line 25, "insulator;" should read -- insulator, --.

COLUMN 22:

Line 53, "electrode;" should read -- electrode, --.

FCHS_WS 1936445v1

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

PATENT NO. 7,265,377 B2

No. of add'l. copies @ 30¢ per page



Form PTO 1050 (Rev. 3-82) 1936445v1(Form#30)